

SERVICE - INFO



**LuK Nr: 133 0608 10 – 330mm DBFP
133 0271 10 – 330mm TBFR**

Bulletin 988 2000 600

NEW HOLLAND FORD – 3000, 4000, 5000 Series & Industrial **

Info:	133 0608 10 replaces / ersetzt / remplace / sustituye a / sostituisce 133 0018 10 133 0271 10 replaces / ersetzt / remplace / sustituye a / sostituisce 133 0017 10
(GB)	When replacing a 4 lever coil spring clutch with LuK diaphragm type clutch, shims are not required.
(D)	Wenn die 4-Hebel-Schraubenfederkupplung durch eine LuK-Tellerfederkupplung ersetzt wird, entfallen die Segmentbleche.
(F)	Le remplacement d'un embrayage à ressorts hélicoïdaux à 4 leviers par un embrayage à diaphragme LuK ne requiert pas de cales de réglage.
(E)	Al reemplazar el embrague de muelles helicoidales con 4 patillas por el de diafragma no es necesario colocar calzos.
(I)	Quando si sostituisce una frizione a molle elicoidali a 4 leve con una frizione di tipo a diaframma LuK, non sono necessari distanziatori.

****** For model information please see LuK Catalogue / Die genaue Fahrzeugzuordnung entnehmen Sie bitte dem LuK-Katalog / Pour les informations le modèle veuillez consulter le catalogue LuK / Para obtener información sobre el modelo, rogamos consulte el catálogo de LuK / Per informazioni sul modello consultare il catalogo LuK

133 0018 10



133 0608 10



133 0017 10



133 0271 10



Issue Level 3