


VABF-S1-P1A11/A12 / VABV-S1-1SB/-2SB

Supply plate / Sub-base



FESTO

Festo SE & Co. KG
Ruiter Straße 82
73734 Esslingen
Germany
+49 711 347-0

www.festo.com

Instructions | Assembly

8110527
2019-04
[8110529]



Translation of the original instructions

1 Applicable documents

 All available documents for the product → www.festo.com/pk.

Documents	Product	Contents
Safety data sheet	Adhesive from the original manufacturer	Loctite 243

Tab. 1

2 Safety instruction

Only assemble the product on components that are in a condition to be safely operated.

3 Product range overview

3.1 Scope of delivery




Fig. 1

3.2 Not in scope of delivery




Fig. 2

4 Assembly




Fig. 3

1. Use a locking agent **3** on the blanking plugs **2**.
2. Screw in blanking plugs **2** so that they are flush.