





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
/ Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

XX = AA, AD...


- 6 A 860 802 XX
- 16 A 962 755 XX
- 17 A 4109 XX
- 19 B 9403 XX
- 21 A 860 807 XX
- 23 A 860 806 XX
- 27 B 9442 XX



IDEALDUO


A 5691 ..




0811 / A 866 430
(+ A 865 612)
Made in Germany



Ideal Standard International BVBA
Chaussée de Wavre, 1789 - box 15
1160 Bruxelles
Belgium

www.idealstandardinternational.com





P bar	T °C	Q (3 bar)		
P bar	T °C	Q (3 bar)		
P bar	T °C	Q (3 bar)		